

ゴムボデーを外した状態での極表示


●適用電線

1CT, 2CT, 2RNCT, 2PNCT	0.75mm <sup>2</sup> ~ 2mm <sup>2</sup> 3心
VCT, S-VCT	0.75mm <sup>2</sup> ~ 2mm <sup>2</sup> 3心
VCTF, S-VCTF	2mm <sup>2</sup> 3心
CTF, RNCTF	1.25mm <sup>2</sup> · 2mm <sup>2</sup> 3心

●適用圧着端子

0.75mm <sup>2</sup> · 1.25mm <sup>2</sup>	R1.25-3.5
2mm <sup>2</sup>	R2-3.5

●電線加工寸法



極配置寸法

